

## R147 Navan Cycle Scheme - Poolboy Bridge to Kells Road

## Tree Survey Summary & Impacts - As a Quantum

#### Impact recommendation

To be removed to facilitate these developments

To be retained with maintenance/mitigation required.

No impact

Т	o	t	a	١	•

Count (Total)	
9	
22	
53	ı
84	

Condition as per Tree Survey				
Good	Fair	Poor		
1	8	0		
3	18	1		
6	46	1		
10	72	2		

# Tree Survey Summary & Impacts - As a Percentage of Scheme Total

## Impact recommendation

To be removed to facilitate these developments	
To be retained with maintenance/mitigation required.	
No impact	

Totals

Count (Total)
11%
26%
63%
100%

Condition as per Tree Survey				
Good	Fair	Poor		
1%	10%	0%		
4%	21%	1%		
7%	55%	1%		
12%	86%	2%		